

WIRING DIAGRAM




Figure O-1 Oven Schematic - Off Condition




Figure O-2 Oven Schematic - Cooking Condition