


Remarks:

L = line,

3 = high speed, 2 = medium speed, 1 = low speed,

O = on/off ⊗ = light



Switch assembly

Motor wiring sketch

